






30	AC LINE	AC INPUT
29	AC NEUT	
28	AC GND	
27	WASH (AC) LINE	
26	WASH NEUTRAL	
25	N/O	
24	C	"B" ALARM
23	N/C	
22	N/O	
21	C	"A" ALARM
20	N/C	
19	RX-	
18	RX+	
17	TX-	ETHERNET
16	TX+	
15	SHIELD	
14	RETURN	
13	TEMP	
12	REF	
11	MEAS	
10	- LED	
9	+ LED	
8	-	0 - 10 V OUT
7	+	0 - 10 V OUT
6	-	4 - 20 mA OUT
5	+	4 - 20 mA OUT
4	-	TEMP OUT
3	+	TEMP OUT
2	-	HOLD TRIG
1	+	HOLD TRIG




PRISM WASH REQUIREMENTS:

$$\text{REQUIRED PRESSURE} = \text{PROCESS LINE PRESSURE} + \text{CHECK VALVE CRACKING PRESSURE} + 30\text{-}45 \text{ (PSI)}$$

T-BOX WIRING DIAGRAM
(SHOWN WITHOUT COVER)

TSS	COLOR	DESCRIP
1	RED	+
2	BLK	-
3	BLK	REF
4	WHT	MEAS
5	GRN	TEMP
6	BLK	RETURN



INTERCONNECTING CABLE
LSC P/N 160706

LIQUID SOLIDS CONTROL, INC.	
DESIGNED BY: John F. Hunsicker	DATE: 9/28/2011
APPROVED BY: [Signature]	DATE: 9/28/2011
DESCRIPTION: M326 SENSING HEAD TO PIPE INSTALLATION	
SCALE: N/A	SHEET # 3 OF 3
PART #	326615